


Esplanade Delille Apt--3rd Party Vibration Monitor Tracking



*Work activities were temporarily halted to allow the site team to evaluate an elevated monitoring reading. The investigation determined that the excavator contacted an unforeseen piece of concrete near the front of the site, located within approximately 15 feet of monitoring instrument L3. Concurrently, monitoring instrument L1 recorded a low level reading of 0.04. Based on these findings, the site team instructed the operator to revise excavation methods in the affected area to minimize disturbance. Following the adjustment, excavation activities resumed, and no subsequent elevated readings or related issues were observed.

All points shown are a momentary reading, not sustained vibration.